




Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0398/19
Category	Protective equipment
Type of alert	Products with serious risks
Product user	Consumer
Product	Via ferrata set
Brand	Ocun
Name	Energy absorber
Type / number of model	VF Torq2 Article 03983
Batch number / Barcode	800940 / 8591804634611
OECD Portal Category	71000000 - Sports Equipment
Description	Via ferrata climbing protection device consisting of two carabiners, linked by a fastener (belt). The product is packed in a bag.
Country of origin	Unknown
Alert submitted by	Luxembourg
Risk type	Injuries
Technical defect	The climbing protection device is not sufficiently resistant to loads.
Risk	The product could break during use, causing the climber to fall and suffer injuries. The product does not comply with the Personal Protective Equipment Directive and the relevant European standard EN 958.
Measures adopted by notifying country	Recall of the product from end users Ban on the marketing of the product and any accompanying measures, Withdrawal of the product from the market
Products were found and measures were taken also in	Poland, Slovenia
	

Images

