



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0457/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Suzuki
Name	Baleno, Swift, Ignis
Type / number of model	Type approval numbers: e6*2007/46*0177*00, e4*2007/46*1205*00, e4*2007/46*1205*00, e4*2007/46*1162*00
Batch number / Barcode	Baleno, model year: 2016/2017, Ignis, model year: 2016, Swift, model year: 2016/2017
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Japan
Alert submitted by	Poland
Risk type	Injuries
Technical defect	Lack of strength of the water pump belt may cause it to break during usage.
Risk	The engine may stall and may not be able to re-start.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Germany, Greece, Hungary, Ireland, Norway, Portugal, Slovenia, Sweden, The Netherlands
Images	No pictures are available