



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0470/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Van
Brand	WW
Name	Crafter
Type / number of model	Crafter NF Type-approval number: e1*2007/46*1613*## Type: SYN1E Code: 53C3
Batch number / Barcode	The vehicles affected were produced between 5 December 2016 and 7 September 2017.
OECD Portal Category	77000000 - Automotive
Description	Van
Country of origin	Poland
Alert submitted by	Germany
Risk type	Injuries
Technical defect	With intensive trailer use, screws attaching the trailer coupling device may become loose.
Risk	This may impair stability in trailer operation and ultimately lead to the entire trailer coupling device becoming detached.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Hungary, Poland, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures are available