



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0514/17
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Professional
Product	Bus
Brand	Evobus
Name	Citaro, CapaCity, Setra, Conecto
Type / number of model	Type-approval numbers: e1*2007/46*0087, e1*2007/46*0090, e1*2007/46*0089, e1*2007/46*0903, e1*2007/46*0097*; types: 628 02,628 03, 628 04, 628 05, 628 21
Batch number / Barcode	The vehicles affected were produced between November 2004 and October 2010.
OECD Portal Category	77000000 - Automotive
Description	Bus
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Risk	When the door action mechanism is disconnected from the power supply, the inward-swinging door has no obstacle detection device via the pressure-wave switch. If a passenger/object happens at that precise moment to be right in the middle of the doorway and is thus not detected as an obstruction, there is a risk that this person/object may become trapped.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Finland, Greece, Portugal, Slovenia, Sweden
Images	No pictures are available