



## Safety Gate: Rapid Alert System for dangerous non-food products

|   |  |
|---|--|
| Alert number  | A12/0552/19  |
| Category  | Motor vehicles   |
| Type of alert                                       | Products with serious risks  |
| Product user  | Professional   |
| Product   | Lorry  |
| Brand   | MAN  |
| Name  | TGS, TGX   |
| Type / number of model                              | Unknown  |
| Batch number / Barcode                              | The vehicles affected were produced between December 2018 and February 2019. |
| OECD Portal Category                                | 77000000 - Automotive  |
| Description   | Lorry  |
| Country of origin                                   | Germany  |
| Alert submitted by                                  | Germany  |
| Risk type   | Injuries   |
| Technical defect                                    | The leaf spring on the front axle could break.                               |
| Risk  | Consequently, driving and steering behaviour could become unstable.          |
| Measures adopted by notifying country               | Recall of the product from end users   |
| Products were found and measures were taken also in | Croatia, Denmark, Hungary, Poland, Slovenia, Sweden                          |
| Images  | No pictures are available  |