



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0622/17
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Van
Brand	Mercedes-Benz
Name	Citan, Sprinter, Viano, Vito, V-Klasse
Type / number of model	Type-approval numbers: Citan: e2*2007/46*0129*, e2*2007/46*0130*; Sprinter: e1*2001/116*0353*, e1*2001/116*0354*, e1*2001/116*0424*, e1*2007/46*0279*, e1*2007/46*0280*, e1*2007/46*0294*, e1*2007/46*0295*, e1*2007/46*0296*, e1*2007/46*0297*, e1*2007/46*0298*, e1*2007/46*0299*, e1*2007/46*0300*, e1*2007/46*0301*, e1*2007/46*0304*, e1*2007/46*0305*, e1*2007/46*0307*, e1*2007/46*0308*, e1*2007/46*0309*, e1*2007/46*0310*, e1*2007/46*0311*, e1*2007/46*0312*, e1*2007/46*0556*, e1*2007/46*0557*, e1*2007/46*0569*, e1*2007/46*1075*, e1*2007/46*1076*, e1*2007/46*1093*; Viano, Vito, V Class: e1*2007/46*0457*, e1*2007/46*0458*, e1*2007/46*0459*
Batch number / Barcode	The vehicles concerned had their control unit updated between 3 and 5 December 2016.
OECD Portal Category	77000000 - Automotive
Description	Van
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Risk	The incorrect update of the control units may result in malfunctioning of the airbag control device, the Electronic Stability Programme or the distance control system.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Estonia, Poland
Images	No pictures are available