



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0756/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Professional
Product	Bus
Brand	Otokar
Name	Territo
Type / number of model	e2*2007/46*0171*01, e2*2007/46*0171*02, e2*2007/46*0171*03, e2*2007/46*0171*04, e2*2007/46*0171*05, e2*2007/46*0171*016 , e2*2007/46*0171*07, e2*2007/46*0171*08, e2*2007/46*0171*09, e2*2007/46*0171*10, e2*2007/46*0171*11, e2*2007/46*0171*12, e2*2007/46*0171*13
Batch number / Barcode	Unknown
OECD Portal Category	77000000 - Automotive
Description	Bus
Country of origin	Turkey
Alert submitted by	France
Risk type	Injuries
Technical defect	The suspension system nuts have been insufficiently tightened.
Risk	They may come loose during driving.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Slovenia
Images	No pictures are available