



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0764/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Pickup truck
Brand	Mercedes-Benz
Name	X-Class
Type / number of model	Type-approval number: E9*2007/46*6531*; type: 4701
Batch number / Barcode	The affected vehicles were manufactured between 01 June 2017 and 13 March 2019.
OECD Portal Category	77000000 - Automotive
Description	Pickup truck under Mercedes-Benz recall code: VS4DACHLA.
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Technical defect	Defective operating manual can cause the roof load to be exceeded if a canopy is subsequently fitted.
Risk	Exceeding the permissible total roof load can impair the correct functioning of the Electronic stability program (ESP) and reduce the driving stability, increasing the risk of an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Finland, Ireland, Luxembourg, Poland, Slovakia, Slovenia, Sweden
Images	No pictures are available