



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0765/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Skoda
Name	Karoq
Type / number of model	Type-approval number: e8*2007/46*0272; type: NU
Batch number / Barcode	The affected vehicles were manufactured between April 2018 and June 2018.
OECD Portal Category	77000000 - Automotive
Description	Passenger car under Skoda recall code: 7219.
Country of origin	Czech Republic
Alert submitted by	Germany
Risk type	Injuries
Technical defect	The locking pin for securing the head restraints may be missing from the central rear seat.
Risk	In the event of an accident, the central rear head restraint may consequently become detached from the guide rods and lose its supportive and protective effect.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Finland, Ireland, Poland, Slovakia, Slovenia
Images	No pictures are available