



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0819/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	BMW
Name	1, 3, X1
Type / number of model	Type-approval numbers: e1*2001/116*0287, e1*2007/46*0273, e1*2001/116*0352, e1*2007/46*0277, e1*2001/116*0287, e1*2007/46*0283, e1*2001/116*0352, e1*2007/46*0277, e1*2007/46*0275, e24*2007/46*0024, e1*2001/116*0308, e1*2007/46*0314, e1*2001/116*0308, e1*2007/46*0315, e24*2007/46*0022, e1*2001/116*0346, e1*2007/46*0316; , types: 187, 1K2, 182, 1C, 187, 1K4, X1, X1-N1, 390L, 3L, 3K, 3K-N1, 392C, 3C
Batch number / Barcode	The affected vehicles were manufactured between December 2009 and October 2011.
OECD Portal Category	77000000 - Automotive
Description	Passenger car under BMW recall code: 0061050500.
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Technical defect	The connector of the positive battery cable on the front power distribution box may be damaged.
Risk	This might result in a failure of the vehicle's electrical system and engine during driving, potentially leading to an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Luxembourg
Images	No pictures are available