



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0924/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Opel
Name	Zafira
Type / number of model	Type-approval numbers: e1*2001/116*0325*00 to *05, e1*2001/116*0325*10 to *11, e1*2007/46*0497*02; types: A-H/Monocab right-hand drive
Batch number / Barcode	The affected vehicles were manufactured between November 2004 and October 2014.
OECD Portal Category	77000000 - Automotive
Description	Passenger car under Opel recall code: E181801310 (19-C-050).
Country of origin	Germany, Poland
Alert submitted by	Germany
Risk type	Fire
Technical defect	A pin contact on the fan motor resistor may melt.
Risk	This can increase the risk of the vehicle catching fire.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Ireland, Luxembourg
Images	No pictures are available