



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1016/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Ssangyong
Name	Tivoli, XLV
Type / number of model	Type-approval number: e9*2007/46*6294*02
Batch number / Barcode	The affected vehicles were manufactured between July 2015 and August 2018.
OECD Portal Category	77000000 - Automotive
Description	Passenger car.
Country of origin	Republic of Korea
Alert submitted by	Belgium
Risk type	Fire
Technical defect	Possible interference between the wiring and the fuel supply line may result in damage of the fuel supply hose and subsequent fuel leaks.
Risk	Fuel leakage close to a source of ignition may increase the risk of the vehicle catching fire.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Finland, Luxembourg
Images	No pictures are available