



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1300/17
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Professional
Product	Lorry
Brand	Van Hool
Name	T9, TX
Type / number of model	types: 91X2L, 92XL, 91X3L, 91XU3F, 91XCLF, 91X2LZ, 91X3LZ
Batch number / Barcode	The vehicles affected were produced from 2010 to 2016.
OECD Portal Category	77000000 - Automotive
Description	Lorry
Country of origin	Belgium
Alert submitted by	Germany
Risk type	Injuries
Risk	A problem with the material of the suspension arm may result in the suspension arm breaking and the loss of a wheel, which could lead to a loss of control over the vehicle.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Denmark, Finland, Sweden
Images	No pictures are available