



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1434/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Professional
Product	Lorry
Brand	MAN
Name	TGA, TGS, TGX
Type / number of model	Type-approval numbers: e4*2007/46*0229*, e4*2007/46*0231*, K681*, K685*; type: L.2007.46.00, L.2007.46.003, TGA02, TGA03
Batch number / Barcode	The vehicles affected were produced between 2001 and 2019.
OECD Portal Category	77000000 - Automotive
Description	Lorry. Recall code 6759TR.
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Technical defect	Due to a limited structural durability, cracks may occur on the front-axle wheel flanges. Such cracks could result in the mounting face of the rim on the front axle rupturing completely.
Risk	This could lead to the loss of a front-axle wheel turning the vehicle uncontrollable.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Finland, Greece, Slovakia, Slovenia
Images	No pictures are available