



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1676/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger vehicle
Brand	Opel
Name	Crossland X
Type / number of model	Crossland X vehicles with D12XE engine (RPO codes LEZ)
Batch number / Barcode	- Model year: 2018 - 2019; - EC-type approval number: e4*2007/46*1194*05, e4*2007/46*1194*06, e4*2007/46*1194*07. - Various VIN numbers
OECD Portal Category	77000000 - Automotive
Description	Passenger car- Recall code: 19-C-090 (E191901510).
Country of origin	Spain
Alert submitted by	Portugal
Risk type	Environment
Technical defect	Due to a software deviation, the lambda (air-fuel ratio) control is not working sufficiently accurate and may cause the exhaust emissions' level of nitrogen oxides (NOx) to exceed regulated limits.
Risk	Nitrogen oxides are harmful to human health and the environment.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Estonia, Finland, Germany, Greece, Luxembourg, Poland, Slovakia, Slovenia, The Netherlands
Images	No pictures are available