



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1727/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Three-wheel motorcycle
Brand	Polaris
Name	Slingshot S / SL / SLR / GT
Type / number of model	Model year 2015 and 2019
Batch number / Barcode	The affected vehicles were manufactured between 15/05/2014 and 25/04/2016.
OECD Portal Category	77000000 - Automotive
Description	Three-wheel motorcycle.
Country of origin	United States
Alert submitted by	United Kingdom
Risk type	Injuries
Technical defect	Under certain conditions, the capability of the battery fuse block terminals might be exceeded by the actual electrical current requirements.
Risk	Consequently, the terminal could be damaged leading to a loss of forward and rear lighting, instrument cluster or power steering assist, increasing the risk of accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Poland, Sweden
Images	No pictures are available