



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1951/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Opel
Name	Combo E
Type / number of model	Type-approval number: e2*2007/46*0623*03, e2*2007/46*0623*04, e2*2007/46*0623*05, e2*2007/46*0623*06, e2*2007/46*0623*07
Batch number / Barcode	The affected vehicles are from model year 2020.
OECD Portal Category	77000000 - Automotive
Description	Passenger cars with RPO code AJ3 (airbag driver side only) under Oper recall code: 19-C-130 (E191904472).
Country of origin	Portugal, Spain
Alert submitted by	Portugal
Risk type	Injuries
Technical defect	The front passenger seat belt may not be correctly installed during production.
Risk	As a result, the seat belt may not retain the passenger sufficiently in the event of an accident, increasing the risk of an injury.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Estonia, Finland, Germany, Luxembourg, Poland, Slovakia, Slovenia
Images	No pictures are available