



Rapid Alert System for dangerous non-food products

| | |
|--|---|
| Alert number | A12/0148/17 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car / van |
| Brand | Dacia |
| Name | Dokker |
| Type / number of model | Type-approval number: e2*2001/116*0314* and e2*2007/46*0030*; type: SD |
| Batch number / Barcode | The vehicles in question were manufactured between 03/07/2015 and 29/09/2016. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car / van |
| Country of origin | Morocco |
| Alert submitted by | Germany |
| Risk type | Injuries |
| Risk | The locking system on the side sliding doors does not work as required. In the event of a collision, the sliding doors may consequently open leading to an increased risk of injury for the passengers. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) |
| Products were found and measures were taken also in | Bulgaria, Croatia, Poland, Portugal, Slovakia, Slovenia, Sweden |
| Images | No pictures available |