



## Rapid Alert System for dangerous non-food products

|  |  |
|--|--|
| <b>Alert number</b>  | A12/0286/16  |
| <b>Category</b>  | Motor vehicles   |
| <b>Risk level</b>  | Serious risk   |
| <b>Product user</b>  | Consumer   |
| <b>Product</b>   | Passenger car  |
| <b>Brand</b>   | Renault  |
| <b>Name</b>  | Kangoo   |
| <b>Type / number of model</b>                              | Kangoo 2 – Gruau conversion. Types: W, FW EC type approvals: e2*2007/46*006*, e2*98/46*0089*   |
| <b>Batch number / Barcode</b>                              | The vehicles affected were produced between 12/11/2009 and 2/9/2014.   |
| <b>OECD Portal Category</b>                                | 77000000 - Automotive  |
| <b>Description</b>   | Passenger car  |
| <b>Country of origin</b>                                   | France   |
| <b>Alert submitted by</b>                                  | Germany  |
| <b>Risk type</b>   | Injuries   |
| <b>Risk</b>  | The fixing bolts for the backrest on the second row of seats may break in the event of heavy braking or a collision. The occupants would consequently not be protected properly. |
| <b>Measures adopted by notifying country</b>               | <b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)   |
| <b>Products were found and measures were taken also in</b> | Netherlands, Portugal, Slovenia, Sweden, Sweden, United Kingdom  |
| <b>Images</b>  | No pictures available  |