



## Safety Gate: Rapid Alert System for dangerous non-food products

|                                       |  |
|---------------------------------------|--|
| Alert number                          | A12/0441/18  |
| Category                              | Motor vehicles                                       |
| Type of alert                         | Products with serious risks                          |
| Product user                          | Consumer   |
| Product                               | Motorcycle   |
| Brand                                 | Horex  |
| Name                                  | Horex VR6  |
| Type / number of model                | Type: VR6  |
| Batch number / Barcode                | The motorcycles concerned were manufactured in 2017. |
| OECD Portal Category                  | 77000000 - Automotive                                |
| Description                           | Motorcycle   |
| Country of origin                     | Germany  |
| Alert submitted by                    | Germany  |
| Risk type                             | Injuries   |
| Technical defect                      | A sensor on the front brake pump may be defective.   |
| Risk                                  | This would result in a decrease in braking action.   |
| Measures adopted by notifying country | Recall of the product from end users                 |
| Images                                | No pictures are available                            |