



Rapid Alert System for dangerous non-food products

Alert number	A12/0471/15
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Passenger car
Brand	Renault
Name	Capture
Type / number of model	e2*2001/116*0327* Types: J5AL, J5A2, J5J5, J5MA, J5MH, J5MW, J5M0, J5M6.
Batch number / Barcode	Production period: from beginning of production (January 2013) until 07/11/2014.
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Spain
Alert submitted by	Portugal
Risk type	Injuries
Risk	Due to wrong assembly of the under-wing plastic protectors, the front flexible brake hose could be damaged resulting in a slow brake fluid leak or sudden bursting of the flexible hose. This could lead to long brake pedal travel and loss of braking efficiency.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Germany, Greece, Hungary, Iceland, Ireland, Norway, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures available