



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0492/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Citroën
Name	C4 Picasso,C4,DS4,C5,DS4
Type / number of model	e2*2007/46*0040*21, e2*2007*46*0040*22, e2*2007*46*0040*23, e2*2007/46*0092*07, e2*2207/46*0092*08, e2*2007/46*0092*09, e2*2007/46*0092*10, e2*2007/46*0092*13, e2*2007/46*0092*14, e2*2007/46*0093*05, e2*2007/46*0356*03, e2*2007*46*0356*04, e2*2007*46*0356*05, e2*2007/46*0356*07, e2*2007*46*0356*08, e2*2007*46*0356*09 e2*2001/116*0360*33
Batch number / Barcode	C4 picasso: manufactured between 5/12/2012 and 21/4/2015, C4-DS4 manufactured between 17/7/14 and 30/4/15 , C5: manufactured between 1/12/2014 and 8/4/2015 , DS5 manufactured between 15/5/2013 and 24/4/2015
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	France
Alert submitted by	France
Risk type	Injuries
Technical defect	Overheating of the engine may occur due to a problem with the engine control software.
Risk	Overheating of the engine may lead to engine failure.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Estonia, Finland, Germany, Ireland, Norway, Poland, Portugal, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures are available