



Rapid Alert System for dangerous non-food products

Alert number	A12/0509/16
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Passenger car
Brand	Nissan
Name	NV200, e-NV200 and X-Trail
Type / number of model	NV200 (M20), e-NV200 (MEO) and X-Trail (T32)
Batch number / Barcode	Model year: NV200 (M20) 2009-2016; e-NV200 (MEO) 2014-2016; X-Trail (T32) 2014-2016
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Japan, Spain
Alert submitted by	Greece
Risk type	Injuries
Risk	The outer tube of the gas strut for the rear door may corrode and crack, resulting in the loss of the pressurized gas inside the gas strut. The gas strut would consequently be unable to support the opening of the rear door and could detach from the vehicle during operation of the rear door.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Distributor)
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Malta, Norway, Portugal, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom
Images	No pictures available