



Rapid Alert System for dangerous non-food products

Alert number	A12/0552/17
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Passenger car / van
Brand	Dacia
Name	Dokker
Type / number of model	Model: Dokker (X67); Type approval numbers: e2*2001/116*0314 ext 80 to 81 and e2*2007/46*0030 ext 38 to 39
Batch number / Barcode	The vehicles in question were manufactured between 30/08//2016 and 11/10/2016
OECD Portal Category	77000000 - Automotive
Description	Passenger car / van
Country of origin	Morocco
Alert submitted by	Portugal
Risk type	Injuries
Risk	The locking system on the side sliding doors does not work as required. In the event of a side impact, the sliding doors may consequently open leading to an increased risk of injury for the passengers.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Distributor)
Products were found and measures were taken also in	Croatia, Finland, Sweden, The Netherlands
Images	No pictures available