



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0552/17
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car / van
<b>Brand</b>	Dacia
<b>Name</b>	Dokker
<b>Type / number of model</b>	Model: Dokker (X67); Type approval numbers: e2*2001/116*0314 ext 80 to 81 and e2*2007/46*0030 ext 38 to 39
<b>Batch number / Barcode</b>	The vehicles in question were manufactured between 30/08//2016 and 11/10/2016
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car / van
<b>Country of origin</b>	Morocco
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	The locking system on the side sliding doors does not work as required. In the event of a side impact, the sliding doors may consequently open leading to an increased risk of injury for the passengers.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Finland, Spain, Sweden, The Netherlands
<b>Images</b>	No pictures available