



Rapid Alert System for dangerous non-food products

Alert number	A12/0561/16
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Van
Brand	Renault
Name	Master
Type / number of model	Master 3. Type: MA, MB, VB, VD, ML; EC type-approval: e2*2007/46*0016*, e2*2007/46*0019*, e2*2007/46*0049*, e2*2007/46*0050*, e2*2007/46*0022*
Batch number / Barcode	Vehicles with an M9T engine, produced between September 2015 and October 2015, are affected.
OECD Portal Category	77000000 - Automotive
Description	Van.
Country of origin	France
Alert submitted by	Germany
Risk type	Injuries
Risk	An oil hose may be incorrectly crimped. If the oil hose becomes completely detached, oil could escape, run on the road and endanger following vehicles.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Products were found and measures were taken also in	Denmark, Ireland, Portugal, Slovenia, Sweden, The Netherlands, United Kingdom
Images	No pictures available