



Rapid Alert System for dangerous non-food products

Alert number	A12/0606/16
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Passenger car
Brand	Renault
Name	Clio
Type / number of model	Clio IV
Batch number / Barcode	e2*2001/116*0327; e2*2007/46*0008. The affected vehicles were manufactured from 15/04/2014 to 06/10/2014 in France and 05/03/2013 to 02/04/2015 in Turkey
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	France, Turkey
Alert submitted by	Malta
Risk type	Injuries
Risk	The front wheel arch may be incorrectly installed. As a result, the brake hose may come into contact with the front wheel arch, causing wear of the brake hose by fretting. If the brake hose breaks and the brake fluid leaks out, the performance of braking could be compromised.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)
Products were found and measures were taken also in	Denmark, Finland, Greece, Norway, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures available