



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0722/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Nissan
<b>Name</b>	Note
<b>Type / number of model</b>	EC type-approval mark: e11*2001/116*0268*03; Type: E11
<b>Batch number / Barcode</b>	The vehicles concerned were manufactured in 2012 and 2013.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	United Kingdom
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Risk</b>	Activation of the driver's airbag may cause an abnormal increase in the internal pressure of the gas inflator and, in extreme cases, cause the casing of the gas inflator to break. This means that there is an increased risk of injury for the occupants.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Croatia, Denmark, Finland, Greece, Ireland, Malta, Portugal, Slovakia, Slovenia, Sweden, The Netherlands, United Kingdom
<b>Images</b>	No pictures available