



Rapid Alert System for dangerous non-food products

| | |
|--|---|
| Alert number | A12/0740/16 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Renault |
| Name | Kangoo |
| Type / number of model | Kangoo II (X61); Types: FW0Z, FW06, FW08 and KW12. EC type approvals: e2*2001/116*0364*37; e2*2007/46*0006*32; e2*2007/46*0089*08 |
| Batch number / Barcode | The affected vehicles have been manufactured between 23 November and 27 November 2015 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger cars. |
| Country of origin | France |
| Alert submitted by | Portugal |
| Risk type | Injuries |
| Risk | The mounting screw of the rear left-hand seat belt return (second row seats) has been incorrectly tightened and could become loose, leading to a loss of protection in case of an impact. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Distributor) |
| Products were found and measures were taken also in | Croatia, France, Germany, Norway, United Kingdom |
| Images | No pictures available |