



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0774/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	VW
<b>Name</b>	Caddy, Golf, Passat, Touran
<b>Type / number of model</b>	Type-approval number: e1*2001/116*0307*##, e1*2001/116*0211*##, e1*2007/46*0627*##, e1*2007/46*0623*##, e1*2007/46*0217*##, e1*2001/116*0252*##; Typ: 3C, 1T, AUV, AU, 2KN, 2K
<b>Batch number / Barcode</b>	The vehicles affected were produced between 22/02/2018 and 27/03/2018.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	Germany
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Technical defect</b>	The fastening of the active headrest may be defective.
<b>Risk</b>	In the event of an accident, the headrest may become detached from the back of the seat, increasing the risk of injury to the person occupying the seat.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Finland, Ireland, Romania, Slovenia, Sweden, The Netherlands
<b>Images</b>	No pictures available