



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0821/17
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motor vehicle part
Brand	MANN+HUMMEL
Name	Unknown
Type / number of model	Type: WK 939/14 x
Batch number / Barcode	Filters from production batch 28816 are affected; production period: August 2016.
OECD Portal Category	77000000 - Automotive
Description	Diesel filter.
Country of origin	Italy
Alert submitted by	Germany
Risk type	Injuries
Risk	The weld seam of the diesel fuel filter may weaken as a result of a defect in the plastic used. As a consequence, the pressure stability of the filter cannot be assured over its service life, which may cause the filter to fail, possibly resulting in a fuel leak with a risk of accidents for other road users.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Sweden
Images	