



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0861/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	VW
Name	Polo
Type / number of model	Type-approval number: e1*2007/46*1783* Type: AW
Batch number / Barcode	Vehicles produced between 29 October 2016 and 23 May 2017 are affected.
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	South Africa
Alert submitted by	Germany
Risk type	Injuries
Technical defect	The buckle for the seat belt for the rear left seat could open unintentionally.
Risk	If this happened, the passenger in the seat would not be protected in the event of an accident.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures are available