



Rapid Alert System for dangerous non-food products

Alert number	A12/0879/16
Category	Motor vehicles
Risk level	Serious risk
Product user	Consumer
Product	Passenger cars
Brand	Nissan
Name	Maxima, Pulsar, Juke, Qashqai and X-Trail
Type / number of model	Models Maxima (A36), Pulsar (C13), Juke (F15), Qashqai (J11) and X-Trail (T32) Type Approval No.: A36: N/A C13: e9*2007/46*3086*00 F15: e11*2007/46*0132*04 J11: e11*2007/46*0963*00 T32: e13*2007/46*1456*07
Batch number / Barcode	Vehicles concerned: Model Year: Maxima (A36) 2015; Pulsar (C13) 2014-2016; Juke (F15) 2014-2016; Qashqai (J11) 2014-2016; X-Trail (T32) 2015-2016 Manufacturing dates: A36: 14/04/2015-05/08/2015; C13: 23/09/2014-26/05/2016; F15: 05/06/2014-25/05/2016; J11: 24/04/2014-16/05/2016; T32: 10/04/2015-07/06/2016
OECD Portal Category	77000000 - Automotive
Description	Passenger cars
Country of origin	Japan, Russian Federation, Spain, United Kingdom
Alert submitted by	Greece
Risk type	Environment
Risk	The sensor of the rear oxygen sensor might fail and does not set a Diagnostic Trouble Code (DTC) in case of inappropriate content of the exhaust gases. In such cases, the user is not warned through the Malfunction Indicator Light (MIL) on the dashboard.
Measures adopted by notifying country	Measures taken by economic operators: Recall of the product from end users (By: Distributor)
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Germany, Malta, Norway, Portugal, Slovakia, Slovenia, Sweden
Images	No pictures available