



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/0879/16
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger cars
<b>Brand</b>	Nissan
<b>Name</b>	Maxima, Pulsar, Juke, Qashqai and X-Trail
<b>Type / number of model</b>	Models Maxima (A36), Pulsar (C13), Juke (F15), Qashqai (J11) and X-Trail (T32) Type Approval No.: A36: N/A C13: e9*2007/46*3086*00 F15: e11*2007/46*0132*04 J11: e11*2007/46*0963*00 T32: e13*2007/46*1456*07
<b>Batch number / Barcode</b>	Vehicles concerned: Model Year: Maxima (A36) 2015; Pulsar (C13) 2014-2016; Juke (F15) 2014-2016; Qashqai (J11) 2014-2016; X-Trail (T32) 2015-2016 Manufacturing dates: A36: 14/04/2015-05/08/2015; C13: 23/09/2014-26/05/2016; F15: 05/06/2014-25/05/2016; J11: 24/04/2014-16/05/2016; T32: 10/04/2015-07/06/2016
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger cars
<b>Country of origin</b>	Japan, Russian Federation, Spain, United Kingdom
<b>Alert submitted by</b>	Greece
<b>Risk type</b>	Environment
<b>Risk</b>	The sensor of the rear oxygen sensor might fail and does not set a Diagnostic Trouble Code (DTC) in case of inappropriate content of the exhaust gases. In such cases, the user is not warned through the Malfunction Indicator Light (MIL) on the dashboard.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Distributor)
<b>Products were found and measures were taken also in</b>	Bulgaria, Croatia, Denmark, Finland, Germany, Malta, Norway, Portugal, Slovakia, Slovenia, Sweden
<b>Images</b>	No pictures available