



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1096/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Mitsubishi
Name	ASX, Outlander, Outlander PHEV
Type / number of model	Type-approval numbers: e1*2001/116*0406*20, e1*2001/116*0406*19, e1*2007/46*0368*05, e1*2007/46*0368*08, e1*2001/116*0406*16, e1*2001/116*0406*21, e1*2007/46*0368*04, e1*2007/46*0368*07, Type: GA0W, GF0W, GG0W
Batch number / Barcode	Model years: 2013 - 2016 (ASX), 2013 - 2016 (Outlander), 2014 - 2016 (Outlander PHEV).
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Japan
Alert submitted by	Poland
Risk type	Injuries
Technical defect	The parking brake lever shaft might be stuck due to corrosion or/and the auto-adjuster of the rear brake piston assembly might be inoperative.
Risk	The parking brake might work with lower efficiency or might be inoperative.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Greece, Iceland, Norway, Portugal, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures are available