



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1164/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	KIA
Name	Niro
Type / number of model	Type-approval numbers: e4*2007/46*1139*00, e4*2007/46*1139*01, e4*2007/46*1139*02
Batch number / Barcode	Manufactured in 2017
OECD Portal Category	77000000 - Automotive
Description	Passenger car
Country of origin	Republic of Korea
Alert submitted by	Poland
Risk type	Fire
Technical defect	Oil might leak on the power electrode inside the hydraulic clutch actuator.
Risk	This may result in a short-circuit, leading to a fire.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Iceland, Slovakia, Sweden, The Netherlands
Images	No pictures are available