



## Safety Gate: Rapid Alert System for dangerous non-food products

|   |  |
|---|--|
| Alert number  | A12/1201/18  |
| Category  | Motor vehicles   |
| Type of alert                                       | Products with serious risks  |
| Product user  | Consumer   |
| Product   | Motorcycle   |
| Brand   | BMW  |
| Name  | F 750 GS (K80) and F 850 GS (K81)  |
| Type / number of model                              | EC-type approval numbers: e1*168/2013*00058 and e1*168/2013*00059;                         |
| Batch number / Barcode                              | Production period: between 18.06.2018 – 03.07.2018.  |
| OECD Portal Category                                | 77000000 - Automotive  |
| Description   | Motorcycle   |
| Country of origin                                   | Germany  |
| Alert submitted by                                  | Portugal   |
| Risk type   | Injuries   |
| Technical defect                                    | The oil pump sprocket might not be correctly screwed on.                                   |
| Risk  | The oil supply to the engine may not be guaranteed and the motor might stall unexpectedly. |
| Measures adopted by notifying country               | Recall of the product from end users   |
| Products were found and measures were taken also in | Croatia, Finland, Germany, Slovenia, Sweden, The Netherlands                               |
| Images  | No pictures are available  |