



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|---|
| Alert number | A12/1335/18 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | MV Agusta |
| Name | F1 B1 B3 |
| Type / number of model | Unknown |
| Batch number / Barcode | Specific motorcycles built between 12/03/2018 and 30/04/2018 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycle |
| Country of origin | Italy |
| Alert submitted by | United Kingdom |
| Risk type | Injuries |
| Technical defect | On some models the fork has an axle carrier with an excessive play of the wheel clamping screw. |
| Risk | This defect could cause a potential malfunction of the fork assembly, which would lead to loss of control of the vehicle during normal use. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Slovenia, Sweden |
| Images | No pictures are available |