



## Safety Gate: Rapid Alert System for dangerous non-food products

|   |   |
|---|---|
| Alert number  | A12/1343/17   |
| Category  | Motor vehicles  |
| Type of alert                                       | Products with serious risks   |
| Product user  | Consumer  |
| Product   | Motorcycle  |
| Brand   | Moto Guzzi  |
| Name  | V7, V9 Bobber, V9 Roamer  |
| Type / number of model                              | Type-approval number: e11*168/2013*00210*; type: LH,<br>Type-approval number: e11*168/2013*00211*; type: KP,<br>Type-approval number: e11*168/2013*00251*; type: LD,<br>Type-approval number: e11*168/2013*00254*; type: KV |
| Batch number / Barcode                              | The vehicles concerned were manufactured between 2016 and 2017.   |
| OECD Portal Category                                | 77000000 - Automotive   |
| Description   | Motorcycle  |
| Country of origin                                   | Italy   |
| Alert submitted by                                  | Germany   |
| Risk type   | Injuries  |
| Risk  | Rubbing of the front brake line against the secondary air system may lead to leakage of the brake fluid for the front brake. Failure of the front wheel brake could lead to an accident.                                    |
| Measures adopted by notifying country               | Recall of the product from end users  |
| Products were found and measures were taken also in | Denmark, Estonia, Finland, Greece, Norway, Poland, Slovenia, Spain, Sweden, The Netherlands   |
| Images  | No pictures are available   |