



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/1354/15
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Renault
<b>Name</b>	Kangoo
<b>Type / number of model</b>	Model: Kangoo II (7 seats); Types: KW0H, KW05, KW06. Type approval: e2*2001/116*0364*
<b>Batch number / Barcode</b>	Production period: February 2012 until 18 June 2014.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car.
<b>Country of origin</b>	France
<b>Alert submitted by</b>	Portugal
<b>Risk type</b>	Injuries
<b>Risk</b>	The third row seats may not lock properly when they are refitted by the user following their removal. This could lead to injuries in case of braking or an impact.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users
<b>Products were found and measures were taken also in</b>	Slovakia, The Netherlands
<b>Images</b>	No pictures available