



## Rapid Alert System for dangerous non-food products

<b>Alert number</b>	A12/1372/18
<b>Category</b>	Motor vehicles
<b>Risk level</b>	Serious risk
<b>Product user</b>	Consumer
<b>Product</b>	Passenger car
<b>Brand</b>	Mercedes-Benz
<b>Name</b>	C-Class
<b>Type / number of model</b>	Type-approval numbers: e1*2001/116*0431*39-45, e1*2001/116*0464*20-22; types: 205, 205 AMG
<b>Batch number / Barcode</b>	The affected vehicles were manufactured between January 2016 and November 2017.
<b>OECD Portal Category</b>	77000000 - Automotive
<b>Description</b>	Passenger car
<b>Country of origin</b>	Germany
<b>Alert submitted by</b>	Germany
<b>Risk type</b>	Injuries
<b>Technical defect</b>	The decorative strips on the rear waist finisher have not been glued on correctly.
<b>Risk</b>	As a consequence they can detach, fall into the road, increasing the risk of accident of the following traffic.
<b>Measures adopted by notifying country</b>	<b>Measures taken by economic operators:</b> Recall of the product from end users (By: Manufacturer)
<b>Products were found and measures were taken also in</b>	Poland, Slovenia, Sweden
<b>Images</b>	No pictures available