



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1382/18
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Passenger car
Brand	Mercedes-Benz
Name	C-class, E-class
Type / number of model	Type-approval numbers: e1*2001/116*0431*46, e1*2007/46*1666*06; types: 205, 238
Batch number / Barcode	Vehicles produced during March 2018 are affected.
OECD Portal Category	77000000 - Automotive
Description	Passenger car. Company recall code: 6290150
Country of origin	Germany
Alert submitted by	Germany
Risk type	Fire
Technical defect	The lower engine compartment cover lacks the necessary left-hand gap for the exhaust system.
Risk	As a result, the exhaust system temperatures resulting from operation at full load could lead to the cover catching fire.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Poland, Sweden
Images	No pictures are available