



Rapid Alert System for dangerous non-food products

| | |
|--|--|
| Alert number | A12/0619/16 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Renault |
| Name | Espace and Talisman |
| Type / number of model | Espace V (JRA4, JRA5, JRME) and Talisman (KPA3, KPA4, KPA5, LPA3, LPA4, LPA5, LPMJ, LPMV). |
| Batch number / Barcode | Production period: until 03/02/2016. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger cars. |
| Country of origin | France |
| Alert submitted by | Portugal |
| Risk type | Injuries |
| Risk | Possible incorrect assembly of the left or right front flexible brake hose could lead to wear of the flexible brake hose by fretting on the wheel rim and on the tyre. Possible brake fluid leakage, which results as a consequence, could lead to long brake pedal travel and a decrease of braking efficiency. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Distributor) |
| Products were found and measures were taken also in | Croatia, Denmark, Estonia, Finland, Poland, Slovakia, Slovenia, Sweden, The Netherlands |
| Images | No pictures available |