



Rapid Alert System for dangerous non-food products

| | |
|--|---|
| Alert number | A12/1362/16 |
| Category | Motor vehicles |
| Risk level | Serious risk |
| Product user | Consumer |
| Product | Passenger car |
| Brand | Renault |
| Name | Espace V |
| Type / number of model | e2*2007/46*0470 ext. 00 to 04 |
| Batch number / Barcode | Vehicles produced between 3 December 2014 and 15 July 2015 and fitted with an R9M Gen 2 engine, index number 452. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Passenger car. |
| Country of origin | France |
| Alert submitted by | France |
| Risk type | Injuries |
| Risk | The exhaust gas recirculation pipe (HP EGR pipe) may crack while the engine is operating. This can lead to hot exhaust gases escaping, which may cause the surrounding parts (cables, hoses, pipes, etc.) to deteriorate. As a consequence, there is a possibility of loss of braking assistance and the stalling of the engine when in motion. |
| Measures adopted by notifying country | Measures taken by economic operators: Recall of the product from end users (By: Manufacturer) |
| Products were found and measures were taken also in | Germany, Portugal, Slovakia, Slovenia, Spain, The Netherlands |
| Images | No pictures available |